

Additional Noise Suppression on pE-100

There have been a small number of occurrences where a pE-100 Control Pod 'locks up' in operation which requires a power down sequence to reset it. This may be caused by adverse electrical noise from some external source. To help with reducing this effect, a ferrite core can be clipped over the cable going between the Pod and the LED head as shown Part No 74271131 (Würth Elektronik)



Place split core ferrite around



Snap shut



Ensure 2 halves are
clipped together cable close to the pod